Approved For Release 2003/01/24 CARDP63-00313A000600100046-5

IDEA-0967

18 December 1962

	MEMORANDUM FOR: Acting Assistant Director, OSA-DD/R
	SUBJECT : 355 Engine Difficulties
	25X1A: Dispatch No. FCWT-0599, from Chief of Base, Subject Monthly Commander's Report November 1962; Para A. 1, Comment Concerning Lack of Recommendations on Engine Problem
	1. Prior to departure from the undersigned with LAC and PW personnel throughly discussed this problem with the Chief of Base. The following conclusions were reached:
	a. P & W and LAC would continue research on an improved P and D Valve to improve and smooth combustion, thereby reducing vibration 25X1D
	b. A reduction in EGT in climb is required to reduce flame out possibility 25X1D
	2. Since my return to Headquarters several cables have been exchanged with contractors concerned, reference the above problem. has been Info Addee on all these cables. 25X1A
25X1A	sent 3. Additionally a summary with progress to date will be this date.
	25X1A
	Maintainance Officer OSA=DD/R